## Message

From: Ewart, Burt [bewart@facil.umass.edu]

**Sent**: 9/20/2012 3:39:17 PM

To: Hanchett, James (DPH) [/O=COMMONWEALTH OF MASSACHUSETTS/OU=MassMail-

01/cn=Recipients/cn=James.Hanchett]

Subject: RE: Exhuast Problem

Jim,

Thanks for the heads-up - I'm not sure what happened, but we are having it checked out.

Burt

## **Burt Ewart**

Capital Project Manager University of Massachusetts Facilities Planning Division 360 Campus Center Way Amherst, MA 01003-9248

## bewart@facil.umass.edu

Direct Extension: 413.577.0128

Mobile:

Office Main: 413.545.1383 Fax: 413.545.3684

From: Hanchett, James (DPH) [mailto:james.hanchett@state.ma.us]

Sent: Thursday, September 20, 2012 9:40 AM

To: Ewart, Burt

Subject: Exhuast Problem

Hi Burt,

You had a problem yesterday with Vivarium exhaust fans. It caused negative pressure in N236. That was the only room affected. We must be connected above ceiling to fish lab. Why else would N236 only be affected?

Jim Hanchett
Department of State Police
Amherst Drug Lab
Room N251 Morrill I
637 North Pleasant Street
Amherst, MA 01003
Phone 413-545-2607
Fax 413-545-2608
Cell